

New York State Department of Environmental Conservation

Division of Environmental Remediation, Region 1

Spill Prevention and Response

50 Circle Road, Stony Brook, New York 11790-3409

Phone: (631) 444-0320 • Fax: (631) 444-0328

Website: www.dec.ny.gov



April 24, 2014

Mr. Batur Gokcan
NJPO, Group
8012 Tonnelles Avenue
North Bergen, NJ 07047

Re: Spill # 10-07938 , 2664 Route 112, Medford, NY

This office has completed a review of Environmental Assessment Remediation (E.A.R) Groundwater and Soil Investigation Report dated March 10 thru 13, 2014 which summarized the work performed at the above referenced location. The soil data suggests the presence of significant petroleum contamination on the site. Therefore this Department is requiring you arrange to perform the following additional work:

Perform a Geo-Probe investigation to define the full nature and extent of the soil and groundwater contamination .

Based on these result, a permanent monitoring network will be installed

Continue to monitor and sample all existing and new monitoring wells on a quarterly basis via EPA method, 602 + MTBE and Fuel Oxygenates.

Please notify me when arrangements have been made to perform this work. If no reply is received within ten (10) days of receipt of this letter, this office will proceed with the investigation, and seek reimbursement plus penalties from you in accordance with **Article 12 of the New York State Navigation Law.**

If you have any questions please call me at (631) 444-0325.

Sincerely,

Nicole M. Hart
Engineering Geologist 1

